

State of Utah DEPARTMENT OF NATURAL RESOURCES DIVISION OF OIL, GAS AND MINING

INSPECTION REPORT

Michael O. Leavitt Governor Kathleen Clarke

Executive Director

Lowell P. Braxton

Division Director

PO Box 145801 Salt Lake City, Utah 84114-5801 801-538-5340

1594 West North Temple, Suite 1210

801-359-3940 (Fax) 801-538-7223 (TDD) Partial: XXX Complete: Inspection Date & Time:

_Exploration: _

10:00a.m.-2:00p.m.

Date of Last Inspection: 9/12/2000

Mine Name: <u>Wildcat Loadout</u> Permittee and/or Operator's Name:	<i>-</i>	Permit Number:
Business Address: P.O. Box 902	1.11.000	
Type of Mining Activity: Undergro		Prep. Plant XXX Other
Company Official(s): Scott Dimic	k	
State Official(s): Bill Malencik	Federal Official(s): None	
Weather Conditions: <u>Clear, 60's</u>		
Existing Acreage: Permitted 100	Disturbed <u>63.7</u> Re	graded Seeded
Status: Exploration Active _	XXX Inactive Temp	porary Cessation Bond Forfeiture
Reclamation (Phase I	Phase II Final Bond Rel	easeLiability Year)

REVIEW OF PERMIT, PERFORMANCE STANDARDS & PERMIT CONDITION REQUIREMENTS

- . Substantiate the elements on this inspection by checking the appropriate performance standard.
 - a. For <u>complete inspections</u> provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check N/A.
 - b. For <u>partial inspections</u> check only the elements evaluated.
- 2. Document any noncompliance situation by referencing the NOV issued at the appropriate performance standard listed below.
- 3. Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
- 4. Provide a brief status report for all pending enforcement actions, permit conditions, Division Orders, and amendments.

		EVALUATED	N/A	COMMENTS	NOV/ENF
1.	PERMITS, CHANGE, TRANSFER, RENEWAL, SALE	Ш	П		
2.	SIGNS AND MARKERS	[X]	\Box	[X]	\Box
3.	TOPSOIL	[X]	П	[X]	\Box
4.	HYDROLOGIC BALANCE:				
	a. DIVERSIONS	[X]	П	[X]	П
	b. SEDIMENT PONDS AND IMPOUNDMENTS	[X]	П	[X]	\Box
	c. OTHER SEDIMENT CONTROL MEASURES	[X]	\Box	[X]	
	d. WATER MONITORING	[X]		[X]	П
	e. EFFLUENT LIMITATIONS	\Box	П	\Box	\Box
5.	EXPLOSIVES	П	[X]	\Box	\Box
6.	DISPOSAL OF EXCESS SPOIL/FILLS/BENCHES		П	\Box	\Box
7.	COAL MINE WASTE/REFUSE PILES/IMPOUNDMENTS	[X]	П	[X]	\Box
8.	NONCOAL WASTE	[X]	\Box	[X]	\Box
9.	PROTECTION OF FISH, WILDLIFE AND RELATED	[X]	\Box	\Box	\Box
	ENVIRONMENTAL ISSUES				
10.	SLIDES AND OTHER DAMAGE	[X]	\Box	\Box	П
11.	CONTEMPORANEOUS RECLAMATION	\Box	\Box	\Box	\Box
12.	BACKFILLING AND GRADING	П		\Box	П
13.	REVEGETATION		П		П
14.	SUBSIDENCE CONTROL	П	[X]		
15.	CESSATION OF OPERATIONS	Ц	\Box	\Box	\Box
16.	ROADS:				
	a. CONSTRUCTION/MAINTENANCE/SURFACING	[X]	\Box		\Box
	b. DRAINAGE CONTROLS	[X]	П	\Box	\Box
17.	OTHER TRANSPORTATION FACILITIES	\Box			\Box
18.	SUPPORT FACILITIES/UTILITY INSTALLATIONS	[X]	\Box	[X]	-[]
19.	AVS CHECK (4th Quarter- April, May, June)	П			П
	AIR QUALITY PERMIT	$\overline{\Box}$	П		
	BONDING & INSURANCE	$\overline{\Box}$	\Box	\Box	\Box

INSPECTION REPORT

(Continuation sheet)

PERMIT NUMBER: ACT/007/033

DATE OF INSPECTION: 10/20/2000

(COMMENTS ARE NUMBERED TO CORRESPOND WITH TOPICS LISTED ABOVE)

2. SIGNS AND MARKERS

All permittee identification signs meet the requirements of the R645 coal rules. The perimeter markers were spot-checked; same are located about the perimeter of all disturbed areas. Wildcat Loadout is not near a stream, and therefore, has no stream buffer zones. All topsoil piles have proper signs for identification.

3. TOPSOIL

The topsoil piles were inspected and no signs of wind or water erosion was evident. These piles are protected by berms and vegetative cover.

4A. HYDROLOGIC BALANCE: DIVERSIONS

The surface drainage diversions were spot-checked and found to be in compliance with the requirements of the mining and reclamation plan and the R645 coal rules. The permittee has cleaned the diversions since the last inspection.

4B. HYDROLOGIC BALANCE: SEDIMENT PONDS AND IMPOUNDMENTS

The sediment ponds were not discharging during the inspection; same contained little or no water. There were no hazardous conditions noted during the inspection relative to any of the site's impoundments.

4C. HYDROLOGIC BALANCE: OTHER SEDIMENT CONTROL MEASURES

The Wildcat Loadout facility uses straw bales as its means of alternate sediment control. The site's ASCA's were spot-inspected and were found to be in compliance with the R645 coal rules. Several straw bales were replaced this summer.

4D. HYDROLOGIC BALANCE: WATER MONITORING

Received a memo prepared by Mr. Smith, Division Hydrologist, assigned to the Wildcat Loadout. Mr. Smith had eight concerns with the monitoring program. Prepared a draft letter for the Division to sign. The letters sends a copy of Mr. Smith's report together with some background information.

INSPECTION REPORT

(Continuation sheet)

PERMIT NUMBER: ACT/007/033

DATE OF INSPECTION: 10/20/2000

7. COAL MINE WASTE/REFUSE PILES/IMPOUNDMENTS

The refuse pile was inspected with no hazardous conditions being noted. The third quarter refuse pile was inspected and was P.E. certified, with no hazardous conditions being reported.

8. NONCOAL WASTE

The area was clear of non-coal waste material.

18. SUPPORT FACILITIES/UTILITY INSTALLATIONS

There have not been any additions to the surface support facilities.

Inspector's Signature: Om Onalenal Date: October 25, 2000

Wm. J. Malencik #26

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas & Mining.

sd

cc: James Fulton, OSM

Mike Glasson, Andalex

Price Field office

 $O:\label{lem:compliance} O:\label{lem:compliance} O:\label{lem:compli$